## SEAWALL REPAIR GENERAL NOTES (Sheets 2, 3, 4, 5 of 8):

- 1. The information presented on these sheets represents the results of a photo survey performed during July of 2003 and can only be considered as indicating the conditions existing at that time.
- 2. Hydroblast granite face stones to remove algae, moss, dirt and other contaminants. Hydroblast in and around joints to remove loose mortar and debris.
- 3. Hydroblast exposed concrete seawall to remove algae, moss, dirt and other contaminants at locations of displaced stones. Manually remove old grout and loose, disintegrated concrete.
- 4. If required, chip back to sound concrete at locations of displaced stones. Replace disintegrated concrete.
- 5. Repair broken granite inset stones.
- 6. Reset displaced and loose stones. Provide new horizontal epoxy coated tie anchors embedded into sound seawall concrete and resting in the mortar beds. Stones to be reset one course at a time. Shore as required.
- 7. Pressure grout only at hard to reach locations above the upper stones after the upper displaced stones are set.
- 8. Repoint the entire length of granite seawall face.

(See specifications.)



US Army Corps of Engineers ®

STATUE OF LIBERTY/ ELLIS ISLAND NATIONAL MONUMENT

> SEAWALL REPAIR ELEVATIONS

South of East Landing Pier (Shuttle Pier) Stations 3+21 TO 1+95

Prepared by: J.Lauletta-Weinmann August 2003 CONTRACT NO. Notes: 1. Station 3+21 northward towards East Landing (Shuttle Pier)
2. Station 3+21 = Station 12+59 (+/-) Reference 1982 As Built Dwgs.

3. Station 1+95 =Station 11+33 (+/-) Reference 1982 As Built Dwgs.

Sheet 2 of 8






US Army Corps of Engineers ®

STATUE OF LIBERTY/ ELLIS ISLAND NATIONAL MONUMENT

> SEAWALL REPAIR ELEVATIONS

> > South of East Landing Pier (Shuttle Pier) Stations 1+95 TO 0+90

Prepared by: J.Lauletta-Weinmann August 2003 CONTRACT NO.



**Notes:** 

- 1. Station 1+95 =Station 11+33 (+/-) Reference 1982 As Built Dwgs.
- 2. Station  $0+90 = \text{Station } 10+28 \ (+/-) \text{ Reference } 1982 \text{ As Built Dwgs.}$

Sheet 3 of 8




US Army Corps of Engineers ®

STATUE OF LIBERTY/ ELLIS ISLAND NATIONAL MONUMENT

> SEAWALL REPAIR ELEVATIONS

> > South of East Landing Pier (Shuttle Pier) Stations 0+90 TO 0+00

Prepared by:
J.Lauletta-Weinmann
August 2003
CONTRACT NO.



Notes: 1. Station 0+90=Station 10+28 (+/-) Reference 1982 As Built Dwgs.

2. Station 0+00=Station 9+38 (+/-) Reference 1982 As Built Dwgs.

Sheet 4 of 8



US Army Corps of Engineers ®

STATUE OF LIBERTY/ ELLIS ISLAND NATIONAL MONUMENT

> SEAWALL REPAIR ELEVATIONS

North of East Landing Pier (Shuttle Pier) Stations 0+00 TO 2+09

Prepared by: J.Lauletta-Weinmann August 2003 CONTRACT NO.

Sheet 5 of 8



Notes: 1. Station 0+00 Commences at Pier.

2. Station  $0+00 = \text{Station } 9+24 \ (+/-)$  Reference 1982 As Built Dwgs.

3. Station  $2+09 = \text{Station } 7+15 \ (+/-) \text{ Reference } 1982 \text{ As Built Dwgs.}$ 



-Photo Detail - 6




Reset displaced stones(typical).



Hydroblast exposed concrete (typical).

Chip back to sound concrete, if required (typical).

Manually remove old grout and loose, disintegrated concrete. Replace disintegrated concrete (typical).



Reset displaced stones (typical).



Hydroblast granite face of stones & Repoint (typical).

Hydroblast exposed concrete (typical).

Chip back to sound concrete, if required (typical).

Manually remove old grout and loose, disintegrated concrete. Replace disintegrated concrete (typical).



Hydroblast granite face stones and Repoint (typical).



Hydroblast granite face stones and Repoint (typical).



**Photo Details - 1 to 4** 

-Photo Details - 5 & 7

Reset Displaced Stones (typical).

Photo 9 Plan Sheet 3 of 8



Photo Detail - 1

Photo Detail 1 Plan Sheet 3 of 8




Photo Detail - 2

**Photo Detail 2 Plan Sheet 3 of 8** 



**Photo Detail - 3** 

Hydroblast exposed concrete (typical).

Chip back to sound concrete, if required (typical). -



Photo Detail - 4

Manually remove old grout and loose, disintegrated concrete. Replace disintegrated concrete (typical).

**Photo Detail - 5** 

Repair broken inset stones (typical).



**Photo Detail - 6** 

**Photo Detail - 7** 

**Existing Grout Pipe**